
How to connect Aricut60/105/120with Thunder X-PRO

The Aricut60/105/120connect to Thunder X-PRO, 4 wires need to be connected.

• The Machine connect terminal:


Machine	Aviation plug	Terminal No.	Description	
	2 0050	START	The CNC plasme are initiation signal	
	2-core	START	The CNC plasma arc initiation signal	
Thunder X-PRO				
connect terminal				
	2 0050	ARC+	The ONO are veloced signal	
	2-core	ARC-	The CNC arc voltage signal	



Aricut60/105/120 Plasma connect terminal:

Note: The customer needs to connect the power cable according to the actual

plasma models;



ℜ Refer to the following table when connecting the Aricut60/105/120 to CNC controller with cable.

Signal	Туре	Notes	Connector sockets
ARC Start	Input	The CNC plasma are initiation signal	1PinControl signal
ARC Start	Input	The CNC plasma arc initiation signal	2PinControl signal
Successful		Normally open. Dry contact closure when	1PinSuccessful Signal
Signal		the arc transfers.	2PinSuccessful Signal
ARC+	Qutout		1Pin Arc Voltage
ARC-	Output	Divided arc signal of 1: 1	2PinArc Voltage

Service Support Spirit

• Cable connecting method:

	Terminal No.	Corresponding interface of	The interface position
		Aricut60/105/12	
	START	1PinControl signal	
	START	2PinControl signal	
Thunder X-PRO			Aricut60/105/12
connect terminal	ect terminal		Interface
	ARC+	1Pin Arc Voltage	
	ARC-	2PinArc Voltage	

• Connect the machine to the plasma signal with terminal blocks:

