

How to restore the system parameter-IPC100


➔ Problem : How to restore the system parameter-X-PRO;

↳ Solution: Step1:Main interface→Press F5 【TOOLS】 into System information→Press F3


【Setup】 into Password interface→then input key 【1396】 --then press enter as show pic3



Pic1




Pic2



Pic3


Step2:In CNC Parameter→Press F7 **【Recovery】** into Restore Parameter interface as show in Pic5;
 Select—The file in folder CNCBackup (This is the file set when the system leaves the factory, If you do not have this document please contact us in time);




Pic4

Step3: Select Restore into next interface → Select **【YES】** Has a successful interface → Press F8 to save;

Note: Please restart the system after settings.



Pic5



Pic6

Service Support Spirit

If you do not have this document please contact us in time;

We will provide an original file, please put this file in the **【CNCBackup】** of the D disk of the computer;

then follow the steps above

