How to do the FORMAT FILE in the CNC system

➜ Problem : How to do the FORMAT FILE in the CNC system;

Problem analysis:

✳ Solution：Step 1- Main interface →Press 【G】【G】【3】on the keyboard Enter

selection interface as below:

Step 2- Press 【Y-】selection 【FORMAT FILE】→Press 【⏎】;

Step 3- Restart the system;