Service Support Spirit



Check the machine power switch –X-MARK

→ Problem: Check the machine power switch;

Problem analysis:

* Please turn on the switch of three positions

Solution: Please turn on the switch;





