

How to solve system G92 error—F2100S

➔ Problem: G92 error occurred in the system;

Solution overview: 1. CNC system parameter setting;


Problem analysis:

✳ 1. CNC system parameter setting;

Solution: Step 1- Main interface → Press F1【AUTO】into AUTO interface→ Press F6【OTHERS】

into assist interface As show pic-1→ Press F2 【WENTAI】 ,Then Deselect WENTAI function.

G92 error resolution.



Pic-1